



RE: Third West Incident Shepherd, Michael to: Craig Barnitz, Joyce Ackerman

02/08/2012 02:24 PM

From:

"Shepherd, Michael" <Michael.Shepherd@PacifiCorp.com>

To:

Craig Barnitz <cbarnitz@utah.gov>, Joyce Ackerman/R8/USEPA/US@EPA

1 attachment

S4522C12020314400.pdf

Craig,

Attached is the incident report from Newman construction and an email from Clean Harbors Environmental Services. Please review and let me know if you have any questions.

Thanks,

Mike Shepherd 801.220.4584 Office 801.631.1310 Cell

From: Craig Barnitz [mailto:cbarnitz@utah.gov] Sent: Tuesday, January 31, 2012 5:55 PM

To: 'Ackerman.Joyce@epamail.epa.gov'; Shepherd, Michael

Subject: Re: Third West Air Monitor Result

Mike,

Do you know if Newman Trucking has developed the follow-up report to the trucking accident that occurred on the 16th of January. Given the Reportable Quantity for asbestos is 1 pound I don't believe a formal report needs to be filed with the state or feds however Joyce and I would like a report to review and to place in the EPA and the UDEQ site files. Just a short summary of the incident would be sufficient (date/time, incident summary, quantity released, remedial actions taken).

Thanks,

Craig

Craig Barnitz **Environmental Scientist Emergency Response/Site Assessment** UDEQ/DERR Phone: (801) 536-0071 Fax: (801) 536-4242

cbarnitz@utah.gov

Joyce & Craig,

We had positive hits on January 26, 2012. All were chrysotile, see the attached. Please let me know if you have any questions or concerns.

Thanks,

Mike Shepherd
Project Manager
Rocky Mountain Power - Major Projects
801.220.4584 Office
801.631.1310 Cell
801.220.2797 Fax
michael.shepherd@pacificorp.com

Call me before you forward

Sent from my Verizon Wireless 4GLTE smartphone

---- Forwarded message -----

From: "Chad Walters" <cwalters@newmanllc.com>

To: "Scott Collard" <Scott.Collard@cve.com>, "Don Johnson" <djohnson@newmanllc.com>

Subject: Newman Construction Date: Tue, Feb 7, 2012 9:27 am

From: James Bleak

Sent: Tuesday, February 07, 2012 9:15 AM

To: Chad Walters

Subject: Fw: Newman Construction

From: Ayers, Ivan M [mailto:ayers.ivan@cleanharbors.com]<mailto:[mailto:ayers.ivan@cleanharbors.com

]>

Sent: Tuesday, February 07, 2012 07:57 AM

To: James Bleak

Subject: Fw: Newman Construction

From: Ayers, Ivan M

Sent: Tuesday, February 07, 2012 06:59 AM

To: Ayers, Ivan M

Subject: Newman Construction

James,

As per our conversation yesterday the following is a brief statement pertaining to the accidental release of asbestos containing material along the frontage road approximately 6 miles from the Grassy Mountain disposal site. As also discussed in our phone conversation, neither I or Clean Harbors Environmental Services will certify that the remediation is complete and meets maximum allowable levels as per state and federal regulations.

On the day in question I was requested to be at the accident site as a consultant and subject matter specialist. Upon arrival, the vehicle recovery process was well underway. I spoke with the Newman's on-site supervisor and discussed with him his remediation options. The options he chose was to remove the wrecked vehicle and trailer, determine the spill size, over dig the area by 12 to 18 inches larger than the actual spill area to a depth of 2 to 4 inches deeper than the spill. The remediated soil was stockpiled and covered by plastic sheeting for later removal the next day.

On the following day when the soil was removed from the site I was not present. Newman Construction did not request my presence, therefore I cannot make a statement as to the actions taken that day. I can however say that I did drive by the area a few days later and notice that a fence that had been torn down during the accident was replaced and the area was landscaped as to appear that nothing had occurred there.

Ivan Ayers
Field Services Foreman
Clean Harbors Environmental Services
2150 North 470 East
Tooele, Utah 84074
Office: 435.843.4860

Cell: 801.718.2925 Fax: 435.843.5612

Email: ayers.ivan@cleanharbors.com<mailto:ayers.ivan@cleanharbors.com>

The information transmitted is intended only for the person or entity to which it is addressed and may contain confidential and/or privileged material. Any review, retransmission, dissemination or other use of, or taking of any action in reliance upon, this information by persons or entities other than the intended recipient is prohibited. If you received this in error, please contact Clean Harbors Environmental Services at 781.792.5555 and delete the material from any computer.

Newman Construction LLC



ACCIDENT REPORT

Accident Date: January 16, 2012

On January 16, 2012 Mike Peterson was loaded at the job site of 400 West 100 South, 3RD West Substation. All safety precautions were taken at this point during the loading, wrapping and covering of the load. He proceeded to leave the site and drive towards the Clean Harbor site at Grassy Mountain. He exited I-80 and proceeded to get on the North Frontage Road. He proceeded west approximately 3 miles where he drifted off the road, when he realized what had happened, he over corrected causing the truck and trailer to begin roiling. Clean Harbor was contacted immediately and they came to the site and supervised the clean-up of the spoils that had been ejected from the truck.







Contractor Safety Report

Report is due by 1:00 p.m. each Wednesday. Please complete form and fax to 503-813-7190 or email to ContractorSafetyInfo@pacificorp.com. Any questions, contact Ryan Meurisse at 503-813-7101.	
Contractor Name: Newman Construction	
Report Date: January 16, 2012	
Company Contact Name and Number: James Bleak / 801-254-3524	
_X_There are no new incidents to report.	
Incident 1	
x Vehicle Incident – Preventable OSHA Recordable Incident Near Miss Lost Time Incident Circuit Interruption	
Employee name: Michael Peterson	
Date of incident: January 16, 2012	
Location of incident: Milepost 49 1-80 North Frontage Road	
Name, title, phone number of person submitting information: James Bleak, Construction Manager, 801 25 3524	54
Description: Driver drifted off the road and totaled the truck and pup that was loaded with spoils from the 3 RD West Substation. Unable to determine why driver drifted off the road.	
Actions taken to ensure incident does not reoccur: DOT training, and refresher courses given on commercial driving.	
Incident 2	
Vehicle Incident - PreventableOSHA Recordable IncidentNear.Miss Vehicle Incident - Non-Preventable Lost Time Incident Circuit Interruption	
Employee name:	
Date of incident:	
Location of incident:	
Name, title, phone number of person submitting information:	
Description:	

Actions taken to ensure incident does not reoccur